

State .. Utah DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil Gas and Mining

JOHN R. BAZA
Division Director

July 12, 2007

Mr. Mike Dalley Staker & Parson Companies 1730 North Beck Street Salt Lake City, Utah 84127-0598

Re: Review of Updated Maps for Five-Year Review of Reclamation Surety Estimate, Staker & Parson Companies, Keigley Quarry, M0490001, Task ID # 1843, Utah County, Utah

Dear Mr. Dalley:

The Division has your updated mine maps for the Keigley Quarry. The four maps were received April 2, 2007. The following is from the Division's August 19, 2003 letter:

The reclamation surety for Staker & Parson Companies' Keigley Quarry is due for review as of 2003. To assist us in this review, we request an updated map of your site showing current surface facilities and disturbances. Please provide the updated map at a scale of not less than 1 inch = 500 feet, which includes: buildings, stationary mining/processing equipment, roads, utilities, power lines, drainage structures (i.e. berms, culverts, etc.), topsoil, ore and product storage areas, overburden/waste dumps, tailings or processed waste facilities, solid and liquid wastes, and wastewater discharge treatment and containment facilities, etc. This map should include all areas which have been affected by this operation to date. Please ignore items listed above which do not apply to your site.

If any reclamation has been completed on the site since the last surety estimate review, please provide a separate map of the same scale as the site map, clearly identifying these reclaimed areas, the acreage affected, and the date of the reclamation. Please cross-hatch or shade the areas to identify the reclamation treatments (i.e. ripping, regrading, mulching, seeding, etc.) which have been applied.

The maps provided do not provide the information requested. Map 1 is of a scale of 1-inch = 800-feet, not the 1-inch = 500-ft. scale or larger as requested. This is also the only map which shows the permit boundary (unlabeled) None of submitted maps include a proper legend or identifies the features listed above.

Page 2 Mike Dalley M0490001 July 12, 2007

Please revise these maps to include a legend, identify the various features, structures, etc. as listed above, and provide a permit boundary (or area to be disturbed and bonded). Please provide the requested update of the plan and maps and an interim reclamation surety in the amount of \$3,000,000 by August 13, 2007. Failure to do so will result in the Division taking enforcement action, possibly closing the mine. If you have any questions concerning this letter, please contact myself at (801) 538-5258 or Lynn Kunzler at 538-5310.

Sincerely,

Susan M. White

Mining Coordinator

Minerals Regulatory Program

Suran M. White

SMW:lk:pb

ce: Daron Haddock, DOGM

P:\GROUPS\MINERALS\WP\M049-Utah\M0490001-KeigleyQuarry\Final\updatedmaps-07092007.doc